

PART - I
PERFORMA FOR THE SAFETY OF INSTITUTION BUILDING
(To be filled by the Head of the Institution)

1. Name of the Institution : Innocent Hearts School
2. Location : Sports & Surgical Complex, Kapurthala Road, Jalandhar
3. Plot Area : 8,119.0029 Sq. Mtrs.
4. Plinth Area : 2,064 Sq. Mtrs.
5. Number of Storey : 2
6. Year of construction of building : 2002
7. If the building has been constructed under the supervision of the Qualified Engineer, the following details may be given
- (a) Name of the Engineer with Qualification : Asst. Mr. B. K. Singhel
- (b) Address of the Engineer : Chatri market, Jalandhar
- (c) Detail of Structural drawings used in the Construction, if available Name & Address of Architect with Qualification : Arch. Mr. B. K. Singhel
Chatri market, Jalandhar
8. Whether the building has been constructed for the purpose of
- (a) Education : Yes
- (b) Residential purpose and converted for use of Institution: N.A.
9. Material used for roofs
- (a) RCC Slabs : Yes
- (b) RS Joists & Battens : N.A.
- (c) Wooden Joints & Battens : N.A.
10. Material used for roofs
- (a) Mud Mortar : NO
- (b) Cement Mortar : Yes
- (c) Plaster i) Lime Mortar : NO
ii) Cement Mortar : Yes
11. Flooring:
- (a) Conglomerate : Yes
- (b) Terrazo : NO
- (c) Brick Paving : NO
12. A detailed drawing indicating dimensions of the rooms alongwith size and location of doors and windows : Attached


Headmistress
Innocent Hearts School
Sports & Surgical Complex,
Kapurthala Road, Jalandhar

Signature and Stamp of the Head of the Institution

PART-II

(TO BE FILLED BY THE S.D.O. OF THE P.W.D. B&R DEPARTMENT)


Innocent Hearts School, Sports & Surgical Complex, Kapurthala Road
Jalandhar

- a) I have visited the above mentioned Institution on 5.4.2023 and I have visually inspected it.
- b) In case any addition/alteration or expansion and modification to this building in to be carried out, the same may be carried out, under the supervision of the technically qualified Engineer and this certificate may again be obtained after the completion from the undersigned.
- c) In case the building is effected by flood or if there is settlement of walls/foundation or sagging of roofs etc. immediate inspection of the undersigned be arranged to check the stability and safety of the building.

- d) This building can be safely occupied for normal use upto (indicate year upto which it can be used) upto 31.3.2024 (2023-2024). The school Building

is VISIBLY SAFE & can be used upto 31.3.2024 (2023-2024).

Ref. No. 02 Dated 5/4/23


Sub Divisional Engineer
Provincial Sub Divn. No.1
PWD B&R Br. Jalandhar Cantt